

## Appendix A : Summary of Statutory Consultation Responses

### Conservation Officer

Latest comments received following revised plans received 16.06.22

This has addressed my concerns – no further objections.

Initial comments received 28.04.22

- As there will be no roof to this memorial, there are concerns over water ingress. The capping on top of the brickwork at the moment appears to be engineering red bricks, which would look wholly out of place. It would be more suitable to find a reclaimed stone capping. The same query applies to the corbelled eaves and capping detail – what is the specification for this?
- The door set into a steel frame is interesting, although this was an internal door and as such I do not know if it would be resilient in an exterior space. What is the methodology for the preservation of the door timber? Would it be through a treatment? I assume there is no future maintenance budget for this?
- Otherwise I think this is an interesting idea and could work well – however the drawings need more detailed specification for capping and the corbelling.